SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 28 04 E25

Horizontal Datum: **NAD 83/91**
Vertical Datum: **NAVD 88**

Established By: H&AI

Control Point ID: **Book:** 614 **Page:** 20 **Pt#:** 01

Date: 11/13/1996

Edited by Geodetic Consultants 01/25/1996
Revised by Geodetic Consultant Consultants 5/05/1997

Section: 12 Township: 28 N Range: 04 E

LATTITUDE: (5 decimal places) **47 56 11.40473**
LONGITUDE: (5 decimal places) **122 13 42.27058**

ORTHOMETRIC HEIGHT: _____ Feet
_____ Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**344706.266**	**1298473.582**	**0.999947245**	**-01 02 19.2**
Meters	**105066.6799**	**395775.5394**		

HORIZONTAL DATA:
Horizontal position established by : H&AI
_____ resection survey, comments _____
_x_ GPS survey, GPS adjustment software used: _____
_____ other, explain: _____
surveyor's estimated relative positional accuracy: ____ .05 ft. @ ___ 95 % confidence
surveyor's estimated absolute positional accuracy: _____ ft. @ ___ % confidence
VERTICAL DATA:
Vertical position established by:
_____ differential leveling to: _____ order accuracy
_____ GPS survey, accuracy within _____ ft _____ meters
surveyor's estimated relative positional accuracy: _____ . ft @ ____ 95% confidence
surveyor's estimated absolute positional accuracy: _____ ft @ _____ % confidence

MONUMENT DESCRIPTION

The monument has been destroyed by sanitary sewer line and manhole construction. The point was calculated from the offset Center line monument, 8 feet North and 8 feet East.

TO REACH

Located at the intersection of Beverly Lane and Madison Street.

REFERENCES

Az from North Distance Reference Description

Month & Year Recovered: Condition of Mark: Recovered By: