SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 29 04 Z17

Horizontal Datum:
Vertical Datum:
Control Point ID: **Book:** **631** **Page:** 25 **Pt#:** 01

Established By: C of E
Date: 09/29/1995
Data sheet edited by Geodetic Consultants 07/96, Revised 05/05/1997

Section: 34 Township: 29N Range: 4E

LATTITUDE: (5 decimal places) **47 56 58.33549**
LONGITUDE: (5 decimal places) **122 16 11.07237**

ORTHOMETRIC HEIGHT: **380.1** Feet
115.85 Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**349647.127**	**1288432.272**	**0.999946554**	**-01 04 10.0**
Meters	**106572.6575**	**392714.9419**		

HORIZONTAL DATA: C of E using Lrica Rapid Static GPS

___ resection survey, comments ___
X GPS survey, GPS adjustment software used: Leica SKI
___ other, explain: ___
surveyor's estimated relative positional accuracy: ___ 02.ft. @ ___ 95 % confidence constrained to City Points E052 and S137
surveyor's estimated absolute positional accuracy: ___ ft. @ ___ % confidence

VERTICAL DATA:
Vertical position established by: C of E
___ differential leveling to: ___ order accuracy
X GPS survey, accuracy within ___ .03ft ___ Meters
surveyor's estimated relative positional accuracy: ___ ft @ ___ % confidence constrained to City Points PAINE and S137
surveyor's estimated absolute positional accuracy: ___ ft @ ___ % confidence

MONUMENT DESCRIPTION

A 5x5 inch pedestal monument with a 1 ½ diameter brass cap and a nail and tag stamped LS 4596, (WEB).

TO REACH

It is located at the intersection of 27th Avenue West and View Crest Avenue. It is in the gravel planter on the west side of the street between the driveways to house numbers 5132 and 2706

REFERENCES

Az from North	Distance	Reference Description
172 degrees	29.0 feet	from a power line pole
43 degrees	20.7 feet	from a sewer manhole
134 degrees	21.4 feet	from the end of the back of the concrete sidewalk

Month & Year Recovered: Condition of Mark: Recovered By: