SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 29 05 R11

Horizontal Datum:
Vertical Datum:
Control Point ID: **Book:** **998** **Page:** 70 **Pt#:** 01

Established By: SNOCO
Date: 02/17/1998
Data sheet edited by Geodetic Consultants 01/25/1998

Section: 28 Township: 29N Range: 5E

LATTITUDE: (5 decimal places) **47 58 41.38220**
LONGITUDE: (5 decimal places) **122 10 24.16879**

ORTHOMETRIC HEIGHT: _____ Feet
_____ Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**359660.932**	**1312224.628**	**0.999945216**	**-01 59 51.7**
Meters	**109624.8713**	**399966.8666**		

HORIZONTAL DATA: Established by SNOCO

_____ resection survey, comments _____
_____ GPS survey, GPS adjustment software used: _____
X other, explain: Traveerse Methods by the Snohomish County Survey Office
surveyor's estimated relative positional accuracy: ___ .05.ft. @ ___ 95 % confidence
surveyor's estimated absolute positional accuracy: ___ ft. @ ___ % confidence

VERTICAL DATA:
Vertical position established
_____ differential leveling to: _____ order accuracy
_____ GPS survey, accuracy within _____ .0ft _____ Meters
surveyor's estimated relative positional accuracy: _____ ft @ _____ % confidence
surveyor's estimated absolute positional accuracy: _____ ft @ _____ % confidence

MONUMENT DESCRIPTION

A 2-inch iron pipe surrounded by 3 metal fence posts under the east bound lanes of U.S. Highway 2 at the intersection of Homeacers Road. Located by using the notes of Mr. Clark Leeman dated 01/29/1997.

TO REACH

REFERENCES

Az from North Distance Reference Description

Month & Year Recovered:	Condition of Mark:	Recovered By:
06/15/1999	Good	PEI