SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 628 32 15

Horizontal Datum: **NAD83/91**
Vertical Datum: **NAVD88**
Established By: **C of E**
Control Point ID: **Book:** 628 **Page:** 32 **Pt#:** 15 **Date:** **07/01/1995**
Edited by Geodetic Consultants 1995. Revised 05/05/1997

Section: 01 Township: 28N Range: 4 E

LATTITUDE: (5 decimal places) **47 56 46.10844**
LONGITUDE: (5 decimal places) **122 13 50.47733**

ORTHOMETRIC HEIGHT: _____ Feet
_____ Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**348232.214**	**1297978.730**	**0.999946729**	**-01 02 25.3**
Meters	**106141.3911**	**395624.7082**		

HORIZONTAL DATA:
Horizontal position established by: The City of Everett.in 1995.
_____ resection survey, comments _____
_X_ GPS survey, GPS adjustment software used: _____
_____ other, explain: _____
surveyor's estimated relative positional accuracy: _____ @ 95% confidence Level
surveyor's estimated absolute positional accuracy @ 1 sigma _____ @ % confidence
VERTICAL DATA:
Vertical position established by:
_____ Differential leveling to: _____
_____ GPS survey, accuracy within ___ .0ft .03 meters
surveyor's estimated relative positional accuracy: ___ ft @ ___ 95% confidence Level
surveyor's estimated absolute positional accuracy: ___ ft @ ___ 95% confidence

MONUMENT DESCRIPTION

A brass pin set in the top of a concrete monument that is set under an iron monument case and cover.

TO REACH

Located at the south end of Highland Road, at house # 5712 Highland Road

REFERENCES

Az from North	Distance	Reference Description
	31.7 feet	from the water valve at the driveway for 5714 Highland Drive
	21.4 feet	south of the center of a sanitary sewer manhole

Month & Year Recovered:	Condition of Mark:	Recovered By:
06/01/199	Good	City of Everett Public Works