SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: V032

Horizontal Datum: **NAD 83/91**
Vertical Datum: **NAVD 88**
Control Point ID: **Book:** 625 **Page:** 51 **Pt#:** 01

Established By: C of E
Date: 10/25/00
Revised by Geodetic Consultants 10-00

Section: 30 Township: 29 N Range: 05 E

LATTITUDE: (5 decimal places) 47 58 35
LONGITUDE: (5 decimal places) 122 12 40

ORTHOMETRIC HEIGHT: **121.391** Feet
36.9999 Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**359173**	**1302950**	**0.999945293**	**-01 01 33.1**
Meters	**109476**	**397140**		

HORIZONTAL DATA:
Horizontal position established by:
_____ resection survey, comments _____
_____ GPS survey, GPS adjustment software used: _____
X other, explain: Horizontal coordinate values have not been established by survey methods. They may or may not be suitable for mapping.
surveyor's estimated relative positional accuracy: _____ ft. @ ____ 95 % confidence
surveyor's estimated absolute positional accuracy: _____ ft. @ _____ % confidence

VERTICAL DATA:
Vertical position established by:
X differential leveling to: 3 order accuracy
_____ GPS survey, accuracy within _____ ft _____ meters
surveyor's estimated relative positional accuracy: _____ ft @ _____ % confidence
surveyor's estimated absolute positional accuracy: _____ ft @ _____ % confidence
Elevation was determined by differential leveling using a Leica Bar-code Level & Starlev software

MONUMENT DESCRIPTION

A 2 inch brass disk stamped, CITY OF EVERETT SURVEY CONTROL STATION 1995 V032. Set in a drill hole flush with the top of the concrete curb.

TO REACH

It is located at the southeast angle of the intersection of Rucker Avenue, (SR 99) and Pacific Avenue.

REFERENCES

Az from North	Distance	Reference Description
	17 feet	from the northwest corner of a retaining wall
	13 feet	from fire hydrant number 441
	3.5 feet	from a catch basin

Month & Year Recovered:	Condition of Mark:	Recovered By:
10/23/2000	**GOOD**	**City of Everett**