SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 28 04 A25

Horizontal Datum: **NAD 83/91**
Vertical Datum: **NAVD 88**

Established By: SNOCO

Control Point ID: **Book:** 1009 **Page:** 50 **Pt#:** 01 **Date:** 02/17/1998

Edited by Geodetic Consultants 01/25/1998

Section: 01 Township: 28 N Range: 04 E

LATTITUDE: (5 decimal places) **47 56 58.14041**
LONGITUDE: (5 decimal places) **122 13 42.62151**

ORTHOMETRIC HEIGHT: _____ Feet
_____ Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**349441.464**	**1298535.539**	**0.999946556**	**-01 02 19.4**
Meters	**106509.9712**	**395794.4239**		

HORIZONTAL DATA:
Horizontal position established by : SNOCO
_____ resection survey, comments _____
_____ GPS survey, GPS adjustment software used: _____
_x_ other, explain: Established by Traverse Observations in 1997 by the Snohomish County Surveyors Office.
surveyor's estimated relative positional accuracy: ____ ..05 ft. @ ___ 95 % confidence
surveyor's estimated absolute positional accuracy: _____ ft. @ ___ % confidence

VERTICAL DATA:
Vertical position established by:
_____ differential leveling to: _____ order accuracy
_____ GPS survey, accuracy within _____ ft _____ meters
surveyor's estimated relative positional accuracy: _____ . ft @ ____ 95% confidence
surveyor's estimated absolute positional accuracy: _____ ft @ _____ % confidence

MONUMENT DESCRIPTION

A 1 inch iron pipe with lead and tack set in a 5x5 inch square concrete monument. This position was established by the Snohomish County Survey Office.

TO REACH

From the intersection of Sunset Lane and 51st Street SW, go east on 51st Street SW to the intersection of Hilltop Road. Go south on Hilltop Road to 5202 Hilltop Road and the point on the right.

REFERENCES

Az from North	Distance	Reference Description
N 30 degrees W	11.44 feet	to the Southeast corner of a house
S 20 degrees W	5.97 feet	to the northeast corner of a garage
	0.25 feet	east of a fence corner post

Month & Year Recovered: Condition of Mark: Recovered By: