SURVEY RECOVERY FORM

City of Everett
Department of Public Works

State of Washington
County: Snohomish

Station Name: 728 46 02

Horizontal Datum: **NAD 83/91**
Vertical Datum: **NAVD 88**
Control Point ID: **Book: 728** **Page:** 46 **Pt#:** 02

Established By: Perteet Eng.
Date: 4/29/2003
Edited by Geodetic Consultants 06/03/2002

Section: 36 Township: 29 N Range: 04 E

LATTITUDE: (5 decimal places) **47 57 21.71068**
LONGITUDE: (5 decimal places) **122 14 06.74595**

ORTHOMETRIC HEIGHT: _____ Feet
_____ Meters

Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	**351859.195**	**1296937.115**	**0.999946229**	**-01 02 37.4**
Meters	**107246.9873**	**395307.2233**		

HORIZONTAL DATA:
Horizontal position established by:
_____ resection survey, comments _____
X GPS survey, GPS adjustment software used: Leica Series 500/Pro
_____ other, explain: _____
surveyor's estimated relative positional accuracy: _____ ft. @ _____ 95% confidence
surveyor's estimated absolute positional accuracy: _____ ft. @ _____ % confidence
VERTICAL DATA:
Vertical position established by:
_____ differential leveling to: _____ order accuracy
_____ GPS survey, accuracy within _____ ft _____ meters
surveyor's estimated relative positional accuracy: _____ ft @ ___ 95% confidence
surveyor's estimated absolute positional accuracy: _____ ft @ _____ % confidence

MONUMENT DESCRIPTION

A nail set in a 2 inch iron pipe in an iron monument case, no lid on case. It is 0.5 feet below the surface. The monument sits on an abandoned road which is now overgrown.

TO REACH

From the intersection of Wood Place and 5th Avenue West go west through the Apartment Entrance to the the west edge of Apartment Building # 1.thence south down the steep slope to the abandoned road to the monument.

REFERENCES

Az from North Distance Reference Description

Month & Year Recovered: Condition of Mark: Recovered By: